

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	379	(print\$4 with laser) and (APC or (automatic near3 power near3 control)) and scan\$5	USPAT	OR	ON	2008/08/15 11:58
L2	39	(print\$4 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5)	USPAT	OR	ON	2008/08/15 13:31
L3	70	(print\$4 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:32
L4	4	(print\$4 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and (error near3 voltage) and integrat\$4	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:45
L5	1	(print\$4 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and ((error near3 voltage) same integrat\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:47

L7	1	(control\$4 with proces\$5 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and ((error near3 voltage) and integrat\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:49
L6	1	(control\$4 with proces\$5 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and ((error near3 voltage) same integrat\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:49
L9	4	(control\$4 with print\$3 with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and ((error near3 voltage) and integrat\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:50
L8	2	(control\$4 with printer with engine) and (APC or (automatic near3 power near3 control)) and (laser near3 scan\$5) and ((error near3 voltage) and integrat\$4)	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 13:50
L10	0	scan\$5 and "6,151,344".pn.	US_PGPUB; USPAT	OR	ON	2008/08/15 14:23

L11	4	(control\$4 with print\$3 with engine) and (APC or (automatic near3 power near3 control)) and (laser withscan\$5) and ((error near3 voltage) and integrat\$4)	US_PGPUB; USPAT; USCOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 14:49
L12	4	(control\$4 with print\$3 with engine) and (APC or (automatic near3 power near3 control)) and (laser with scan\$5) and ((error near3 voltage) and integrat\$4)	US_PGPUB; USPAT; USCOR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/15 14:51

8/15/2008 4:03:14 PM

C:\Documents and Settings\dforde\My Documents\EAST\Workspaces\10646923.wsp